

TOWN OF ESSEX

APPLICATION FOR CERTIFICATE OF OCCUPANCY

No. 1253-87, 1987

The undersigned herewith requests an inspection of the premises and the issuance of "Certificate of Occupancy" of premises, or portion thereof, for use or habitation.

This request is for use only of existing land or buildings.

This request is for new construction or rehabilitated or altered structure which was done under authority of building/zoning permit # 1255-87

issued 7/8, 1987 to EDWARD + MARY LOU HURLEY
(NAME)

Premises are at 291 OLD STAGE RD, ESSEX JCT, VT 05452
(STREET ADDRESS)

Applicants Mailing Address (If different) _____

Driveway location inspected and approved by HA D. Lutz

Water service installation inspected and approved by HA private

Sanitary sewer connection or septic system inspected and approved by:

FITZPATRICK + LLEWELLYN, INC. 1/13, 1988
(NAME) SEE ATTACHED (DATE)

Construction was begun 8/1/87, 1987 and completed 12/1/87, 1987

Actual cost of construction \$ 175,000

Approval granted by _____ Planning Commission Zoning Board of Adjustment 7/9, 1987.

Use of premises intended SINGLE FAMILY DWELLING
(What will you use the new bldg. addition or alt. for)

Daytime phone # 864-0781, 2/26, 1988
(DATE)

Edward D. Hurley
(Applicant's Signature)

Certificate of Occupancy approved with _____ without conditions.

Certificate of Occupancy denied _____. Please see attachment with reasons for denial.

March 4, 1988

Jay Z. Finkel
Zoning Administrator
Town of Essex, Vermont

FITZPATRICK-LLEWELLYN INCORPORATED

Engineering and Planning Services

One Wentworth Drive • Williston • Vermont • 05495 • (802) 878-3000

13 January 1988

Ms. Mary Clark
Agency of Natural Resources
111 West Street
Essex Junction, VT. 05452

RE: Edward Hurley, Old Stage Road
Essex, VT.
Case No. EC-4-0823-3
FILE: 87092

Dear Ms. Clark:

As required in the conditions of the above-referenced permit, we are hereby certifying that the mound system was built in substantial accordance with the plans, with the following referenced notations:

- The location of the bed, as constructed, is according to the plan.
- The pump station control box and alarm system was not in place at the time of inspection.
- The pump station cover was not installed at the time of inspection.
- 1/4" diameter orifices had been enlarged to 5/16" as specified and approved.
- 1/4" diameter drain hole in bottom of manifold has been eliminated, as specified and approved.
- Results of the sieve analysis are enclosed, we feel that they are in substantial compliance with the regulations.
- Flow testing of the laterals revealed an orifice discharge of 1 psi or 2 gallons per minute per orifice. Variation between "nearest and farthest" orifice flows was less than 15%.
- The curtain drain was located and constructed according to the plans.
- All other aspects of the mound construction have been built in substantial accordance with the approved drawings D-880 & D-881, last revision dated May 1984, and D-882 last revision dated February 1984.
- All other aspects pertaining to the pump station have been constructed in substantial accordance with the approved drawings C-2220 dated July 1987.

Should you need additional information or clarification, please contact us.

Sincerely,

FITZPATRICK-LLEWELLYN INCORPORATED


Charles Van Winkle