

TOWN OF ESSEX

APPLICATION FOR CERTIFICATE OF OCCUPANCY

NO. 92-90

July 25, 1990

The undersigned herewith requests an inspection of the premises and the issuance of "Certificate of Occupancy" of premises, or portion thereof, for use or habitation.

[] This request is for use only of existing land or buildings.

[X] This request is for new construction or rehabilitated or altered structure which was done under authority of building/zoning permit # 92-90

issued MAY 7, 1990 to STEVE BAKER/JOHN BURROUGHS

Premises are at PETTINGILL ROAD

Water service installation inspected and approved by VT. DEPT OF HEALTH LAB.

Driveway location inspected and approved by PRE-EXISTING CURB CUT

Sanitary sewer connection or septic system inspected and approved by:

WHEELER ENGINEERING JULY 25 1990
Name Date

Construction was begun MAY, 1990 and completed JULY 24, 1990

Actual cost of construction \$ _____

Approval granted by: Planning Commission Zoning Board of Adjustment

FEBRUARY, 1989.

Use of premises intended RESIDENTIAL PRIMARY HOME
(Type of Use)

Land was conveyed by _____ and is recorded in Vol _____
(Type of Deed)

page _____ of the Town of Essex Land Records by _____
(Grantee) (Granter)

to _____, 19____
(Grantee) (Date)

Steve Baker
Applicant's Signature

Certificate of Occupancy approved with _____ without conditions

If with conditions, see attachment outlining same.

Certificate of Occupancy denied _____. Please see attachment with reasons for denial.

July 25, 1990
Date

[Signature]
Zoning Administrator, Town of Essex, VT

RICHARD WHEELER
WHEELER ENGINEERING
WATERBURY CENTER, VERMONT

P.O. BOX 71
WATERBURY CENTER, VT 05677

(802) 244-8061

GUNNER McCAIN
ASSOCIATE

July 25, 1990

John Burroughs & Steve Baker
30 Saybrook Road
Essex Jct., VT 05452


Re: Everett Stygles Lot #3
Pettingill Road
Essex, VT

Dear John & Steve,

I have inspected the septic system on the above lot and found that it was constructed substantially according to the Plans and in a workmanlike manner. Due to ledge between the house and septic system, a pump chamber was installed to deliver the effluent to the system. The pump operated satisfactorily.

Please call if you have any questions.

Sincerely,


Gunner McCain

cc: file

*Please put
this with the
septic permit*