

TOWN OF ESSEX CERTIFICATE OF OCCUPANCY APPLICATION

MAP/PARCEL/LOT: _____

NO. 154-97

The undersigned herewith requests an inspection of the premises and the issuance of "Certificate of Occupancy" of premises, or portion thereof, for use or habitation.

- This request is for use only of existing land or buildings.
- This request is for new construction or rehabilitated or altered structure which was done under authority of zoning permit # 154-97

Issued 7-9, 1997 to Greg Wolf & Laura Pellegrini

Premises are at 67 Old Pump Rd.

Water service installation inspected and approved by private

Driveway location inspected and approved by Jeff Arthur

Sanitary sewer connection or septic system inspected and approved by: See attached Certificate

Name: See letter from Brig McCain Date: _____

Construction was begun 7-9, 1997 and completed 9-30, 1997

Approval granted by _____ P.C. or Z.B.A. _____ on _____, 19____.

Use of premises intended Single Family Home
(type of use)

Applicant's Signature: [Signature] Telephone: 862-6807

Builder - Bill Allen Bldg Coy
By issuance of this Occupancy Permit, the Town of Essex Zoning Administrator hereby acknowledges that the use and/or building construction is in complete conformity with the Zoning Regulations, unless otherwise noted. Field measurements and similar dimensions for setbacks are based in part on evidence supplied by owner. The Town of Essex is not liable for errors or mistakes when it is found that information submitted by the applicant is erroneous or inaccurate.

Certificate of Occupancy has been approved with _____ without 2 conditions.
If with conditions, see attachment outlining same.

Certificate of Occupancy denied _____. Please see attachment with reasons for denial.

10/3/97
Date

[Signature]
Jerry L. Firkey, Zoning Administrator

MCCAIN CONSULTING

ENVIRONMENTAL CONSULTING AND DESIGN
93 SOUTH MAIN STREET • WATERBURY, VT 05676
(802) 244-5093 TEL • (802) 244-7492 FAX

September 26, 1997

Sherm Webster

Re: Septic System Inspection
Burde Lot #3, Essex

To whom it may concern,

Please be informed that I have inspected the septic system as constructed to serve the house on the above mentioned lot and found that the system was constructed substantially according to the plans and in a workmanlike manner. The pump station delivering effluent to the distribution box was tested and performed adequately.

At the time of my inspection the remaining work to be done included covering the system with filter fabric, final covering, and grading of the area.

Please feel free to call if you have any questions.

Sincerely,



Brig McCain
for Gunner McCain